

# tech.topic

## Fundamentals and Troubleshooting for HMW-HDPE Blown Film Extrusion

High molecular weight high density polyethylene (HMW-HDPE) blown film is steadily growing in use as processors push their lines ever harder to attain greater throughputs. The higher the line speed the more critical it is to heed and understand line performance. Any film problems can generate huge amounts of scrap if not caught and remedied quickly.

The optimal extrusion equipment for HMW-HDPE is a grooved feed extruder. The grooved feed section ensures a positive “bite” of the solid pellet against a barrel wall and prevents this non-tacky material from rolling around on itself. This is the entire theory behind a grooved feed system.

To ensure optimal bite and provide consistent throughput, the grooved feed systems is shrouded in a cooling jacket. The jacket is expected to have between 3-5 gallons of water at between 60° -85°F circulated through it per minute. If the jacket is kept cooler bridging problems can occur during idle time (i.e., screen changes). If the jacket is kept hotter, melting into the grooved feed section can begin prematurely, reducing feed which results in a loss of throughput.

There is no standard heat profile. The heats can be optimized by setting them as cold as you can without producing overrides or high pressures. For an unknown HMW-HDPE resin it is recommended that a straight profile of 400°F be set across the entire system. Once a mT (melt temperature) has been established, set the feed zone at mT-30°F, the second zone at mT-20°F and the rest of the barrel at mT. Always set the die slightly hotter to aid in a smooth flow through the die without creating additional pressure.

For an extruder with limited cooling, an offset reverse of 390°, 400°, 390°, 395° may be used in order to keep the cooling fan on. Remember that zones are adjustable and meant to be changed. Adjust zones based on what you see (i.e. melt fracture, mT changes, etc.). Always run as cold as possible to gain maximum efficiency from the grooved feed and allow the largest rate limiting area (cooling) to be more efficient.

For HMW-HDPE the typical blow up ratios (BUR) are 3.5-4.5:1. BURs may be varied depending on the film properties desired for the product being produced. The larger the BUR, the higher the machine direction tear. The lower the BUR, the higher the transverse direction tear value. The neck height (long stalk) for most resins is six to nine times the die diameter. This height is needed to allow relaxation of the polymer chains and maximize the inherent strengths of the resin. The neck height may be varied, same as the BUR may be varied, depending on the film properties desired. The higher the neck the higher the machine direction tear value and the lower the transverse direction tear value. The reverse is also true. One caveat is that you may increase the MD tear value from 6 grams to 9 grams, because of the morphology of HMW-HDPE, much like raw spaghetti, its polymer chains are basically in a straight line in the machine direction.

For those extruders that depend on a contact stabilizer for orientation, some of these rules may or may not apply. Whether you have experience in this art or are just beginning, there are fundamental steps that need to be followed to maximize this system. The chart on Page 2 describes some of the steps necessary to troubleshoot this type of system.

Make sure all main indicators are accurate, especially the mT and mP probes (melt pressure), temperature gauges, screw and primary nip speeds. Without a road map of the process, you won't know which way to steer the extruder. The result of these devices not working properly is downtime, scrap and the safety of you and those around you.

There is a distinct relationship between heat and pressure. Whenever there is a need to make an adjustment, be sure of the direction and the result you expect to achieve based on the heat/pressure relationship.

*(Continued on Page 2)*

# tech.topic

## Fundamentals and Troubleshooting for HMW-HDPE Blown Film Extrusion

Problems	Possible Causes	Comments
In Barrel & Screw Zone Overrides	Overshear in one or more zones	Raise heat zones above override. Check controllers
Throughput Loss	Cooling Jacket	<ul style="list-style-type: none"> <li>■ Insure there is adequate flow (3-5 gal/min)</li> <li>■ Insure water temperature is within guidelines of the OEM</li> </ul>
	Bridge in Feed Section of Screw	<ul style="list-style-type: none"> <li>■ Make sure cooling jacket is not too cold to freeze resin.</li> <li>■ Check material entering feed throat</li> </ul>
	First Screw Flight out of Grooved Feed Section is Worn	Accompanied by increase in mT and decrease in mP
In Die: Port Flow	Melt temperature may be too low	<ul style="list-style-type: none"> <li>■ Raise die temps in 5 degree increments until lines disappear.</li> <li>■ If flow is too high through the ports raise die center and lower die exit.</li> <li>■ Check controllers and heater bands</li> </ul>
Die Lip Buildup	Burned polymer or low molecular weight wax	<ul style="list-style-type: none"> <li>■ Lower die temperatures if possible</li> <li>■ Check heat stability of polymer</li> </ul>
	Catalyst Residue in Polymer	<ul style="list-style-type: none"> <li>■ Contact resin supplier</li> </ul>
In the Bubble Gauge Variations	Die not Adjusted Properly	<ol style="list-style-type: none"> <li>1. Stop Rotation/Oscillation</li> <li>2. Loosen Belly</li> <li>3. Tighten Flat Side</li> <li>4. Take Another Sample</li> <li>5. Finger Tighten Loose Bolts when Finished</li> </ol>
	Drafts Around Bubble	High stalk bubbles are especially sensitive to air currents
	Too Much Torque to Move Adjusting Bolts	<ol style="list-style-type: none"> <li>1. Shut Extruder Down</li> <li>2. Remove Die Pin</li> <li>3. Remove and Clean Adjusting Ring</li> <li>4. Anti-Seize Bottom of Adjusting Ring</li> <li>5. Lower onto die proper and wait 20 minutes</li> <li>6. Rotate 180 degrees &amp; retorque to proper nm</li> <li>7. Reinstall Die Pin and Retorque</li> </ol>

# tech.topic

## Fundamentals and Troubleshooting for HMW-HDPE Blown Film Extrusion

Problems	Possible Causes	Comments
In the Bubble Gauge Variations <i>(Continued)</i>	Drive or Control Cabinet Overheating  Running High Speed Line at Slow Speeds  Variable Additions of Regrind	<ul style="list-style-type: none"> <li>■ Measure to assure consistent voltages</li> <li>■ Consider air conditioning cabinets</li> </ul> Variation specifications are exacerbated at low speeds  Pellet cuts or flakes alter feed zone bulk and blending percentages
Surging in Machine Direction	Too Much Tension Overdriving Primary Nip  Poor Drive Speed Regulation  Partially Seized Bearings  Loose Sprockets	Check nip motor for surging; check nip roll pressure. Ensure slaved units are within trip speeds  Too Large a window presents gauge variation, especially in conjunction with slow speeds  Ensure bearings are lubricated and all rollers spin freely  Slippage will not keep constant tension across film width
Surging In Transverse Direction	Die Problems  Air Ring Problems  Environmental Problems	<ol style="list-style-type: none"> <li>1. Check Die Adjustment</li> <li>2. Center die under nips when hot</li> <li>3. Level die under nips when hot</li> <li>4. Check for excessive degradation on die and/lips</li> </ol> <ol style="list-style-type: none"> <li>1. Air ring not centered</li> <li>2. Air ring not level</li> <li>3. Air ring dirty</li> <li>4. Poor air ring design</li> <li>5. Air leaks through hoses, connections, etc.</li> <li>6. Uneven hose lengths</li> </ol> <ul style="list-style-type: none"> <li>■ Heat from surroundings, i.e. cooling fans, blowers, compressors, lights, etc.</li> <li>■ Drafts on stalk from open doors, windows, air conditioning vents</li> </ul>
Bubble Breaks	Clear Gels  Burned Gels	Lower feed zone temp to increase shear and raise barrel exit slowly until gels disappear  <ul style="list-style-type: none"> <li>■ May not be able to avoid die cleaning</li> <li>■ Try raising die heats to flow over burned, hard particulates</li> <li>■ Check for runaway die heats</li> <li>■ Check heat profile</li> <li>■ Don't allow extruder to sit for long periods of time without turning the screw</li> </ul>



# tech.topic

## Fundamentals and Troubleshooting for HMW-HDPE Blown Film Extrusion

Problems	Possible Causes	Comments
Bubble Breaks ( <i>Continued</i> )	<p>Low Melt Strength</p> <p>Extrudate Looks Cold</p>	<ul style="list-style-type: none"> <li>▪ If breaks occur without an assignable cause, check antioxidant content</li> <li>▪ Have your resin package checked by your material supplier</li> <li>▪ Ensure die heater bands are not lined up, causing cold spots</li> <li>▪ Ensure controllers and heater bands are in proper working condition</li> </ul>
In Take Off: Uneven Roll	<p>Rotation/Oscillation Issue</p> <p>Tower Height</p> <p>Collapsing Frame</p> <p>Dryer Heat</p>	<ul style="list-style-type: none"> <li>▪ Ensure bubble guiding cage, collapsing frame and tower are aligned and trammed</li> <li>▪ Guide HMW-HDPE, squeezing it may cause wrinkles</li> </ul> <p>Check if film is too hot or too cold at primary nip</p> <ul style="list-style-type: none"> <li>▪ Check alignments; ensure rollers spin freely. Use styles that offer the lowest COF for films being produced</li> <li>▪ Stabilizer bars and bubble cages must be symmetrical without vibration</li> <li>▪ Ensure no air entrapment through primary nip</li> <li>▪ Is one side of the web hotter than the other? If so, elongation will occur.</li> </ul>



Before using a product sold by a company of the LyondellBasell family of companies, users should make their own independent determination that the product is suitable for the intended use and can be used safely and legally. SELLER MAKES NO WARRANTY; EXPRESS OR IMPLIED (INCLUDING ANY WARRANTY OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE OR ANY WARRANTY) OTHER THAN AS SEPARATELY AGREED TO BY THE PARTIES IN A CONTRACT.

LyondellBasell prohibits or restricts the use of its products in certain applications. For further information on restrictions or prohibitions of use, please contact a LyondellBasell representative. Users should review the applicable Safety Data Sheet before handling the product.

LyondellBasell Industries  
P.O. Box 3646  
Houston, TX 77252-3646  
United States

*Adflex, Adstif, Adsyl, Akoafloor, Akoalit, Alathon, Alkylate, Amazing Chemistry, Aquamarine, Aquathene, Arcopure, Arctic Plus, Arctic Shield, Avant, Catalloy, Clyrell, CRP, Crystex, Dexflex, Duopac, Duoprime, Explore & Experiment, Filmex, Flexathene, Glacido, Hifax, Hiflex, Histif, Hostacom, Hostalen, Ideal, Integrate, Koattro, LIPP, Lucalen, Lufflexen, Lupolen, Lupolex, Luposim, Lupostress, Lupotech, Metocene, Microthene, Moplen, MPDIOL, Nerolex, Nexprene, Petrothene, Plexar, Polymeg, Pristene, Prodflex, Pro-Fax, Punctilious, Purell, SAA100, SAA101, Sequel, Softell, Spherilene, Spheripol, Spherizone, Starflex, Stretchene, Superflex, TBAC, Tebol, T-Hydro, Toppyl, Trans4m, Tufflo, Ultrathene, Vacido and Valtec* are trademarks owned or used by the LyondellBasell family of companies.

www.LYB.com

*Adsyl, Akoafloor, Akoalit, Alathon, Aquamarine, Arcopure, Arctic Plus, Arctic Shield, Avant, CRP, Crystex, Dexflex, Duopac, Duoprime, Explore & Experiment, Filmex, Flexathene, Hifax, Hostacom, Hostalen, Ideal, Integrate, Koattro, Lucalen, Lupolen, Metocene, Microthene, Moplen, MPDIOL, Nexprene, Petrothene, Plexar, Polymeg, Pristene, Pro-Fax, Punctilious, Purell, Sequel, Softell, Spheripol, Spherizone, Starflex, Tebol, T-Hydro, Toppyl, Tufflo and Ultrathene* are registered in the U.S. Patent and Trademark Office.